Oil Field Environmental Incident Summary

Incident: 20140830185843 Date/Time of Notice: 08/30/2014 18:58 Responsible Party: Loenbro **ONEOK ROCKIES MIDSTREAM** Well Operator: Well Name: Field Name: CATWALK Well File #: Date Incident: 8/30/2014 Time Incident: 00:09 Facility ID Number: **WILLIAMS** Rna: 100 Sec: 10 Qtr: County: **Twp:** 155 Location Description: Two miles East of the intersection of County road 9 and 58th street NE. On the south of 58th where pipeline ROW crosses 58th. Submitted By: Tye Whitlock Received By: Contact Person: Tye Whitlock 5831 Epping, ND 58843 General Land Use: Badlands Terrain Affected Medium: Topsoil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Other Release Contained in Dike: Unknown Reported to NRC: Yes Units Spilled Recovered Units Followup Units Oil **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: Immediate risk to human safety at this time is low. Line has been shut down. Areal Extent:

Potential Environmental Impacts:

Could be some soil contamination

Action Taken or Planned:

Spill was limited to condensate emission from pipeline. Line was shut in ASAP and will continue to be shut down til repairs are made. All personnel were evacuated immediately as well as the public.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 9/2/2014 Status: Reviewed - Follow-up Required Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill occurred along pipeline right of way. Followup is necessary.

Date: 9/3/2014 Status: Inspection Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 4:00 p.m. The weather was overcast with wind out of the NE at 10-15 mph. The area of impact was located on the south side of 58th Street NE on the pipeline right of way. The area of impact is about 500 ft X 600 ft in very steep and hilly terrain pasture area and the pipeline right of way. The top of the hill, pipeline right of way, and pasture area have been scraped, and the soil has been piled up for disposal. The contractor is investigating a way to clean up the steep slopes. More followup will be needed.

Date: 9/9/2014 Status: Inspection Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 18:35, off site 18:55, windy, 45 degrees, overcast. Site has been nearly completely reshaped. Good erosion control in place. Collected pictures.

Date: 9/19/2014 Status: Correspondence Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Contacted company rep on Sept 19 and was informed the area of impact had been cleaned up and soil removed for disposal. Company had scraped up the impacted soil and installed erosion control for the hill sides. Company will monitor area to ensure growth of vegetation next spring. Company did send a follow-up report to Oil & Gas.